





CRS-6200 Bill Loading Procedure

In order to avoid jams, it is important to correctly load the hopper. Cassida recommends not to use more than 200 bills at a time. Follow the 3-step loading technique below to ensure smooth bill feeding.


STEP 1:

Correct or remove the bills that are severely wrinkled, damaged or folded. Square the bill stack.




STEP 2:

Adjust the bill guides to a size slightly wider than the width of the bills. Make sure the bill stack is square, as shown in the diagrams on the right & below.





CRS-6200 Bill Loading Procedure



STEP 3:

See diagrams below for proper bill feeding. Please note, the unit will start counting automatically (unless in manual mode)

