



CRS-7500

External Printer Connection

The Cassida CRS-7500 provides the option to display the report on the screen and print it if external printer is connected (printer not included).

Below please see instructions on how to connect external printer to the CRS-7500.

1. Please connect the printer to the DE-9 (DB-9) port at the back of the CRS-7500.



2. After the connection process is successfully done, make sure the CRS-7500 and the printer are both on. Count the stack of mixed denomination bills, when done, press report button on the display and then print button to print the report displayed on the screen.
3. If you have any issues with the connectivity of the printer, please contact us any time at www.cassidausa.com/pages/crs-7500-mixed-bill-counter-faq